

### **ABSTRACT**

Highways Department – Announcement made by Hon'ble Finance Minister during the budget speech 2017-2018 – For Carrying out the works under Road Safety Component - Sanctioned – Change in Nomenclature and – Approved - Orders – Issued.

Highways & Minor Ports (HN.2) Department

G.O. (D) No. 83

Dated: 30.05.2019

விகாரி, வைகாசி 16, திருவள்ளுவராண்டு 2050

#### Read:-

- 1. G.O.(D) No.48, Highways and Minor Ports (HN2) Department, dated 12.06.2017.
- 2. From the Chief Engineer (C&M), Highways Department Letter No.7258 / Salai / 2018 dated 11.01.2019.

#### ORDER:

In the Government Order first read above, Government have accorded Administrative Sanction for a sum of Rs.100 Crore for carrying out 700 Number of works under Road Safety component.

- 2. The Chief Engineer (Construction and Maintenance), Highways Department has now furnished the proposal for Change in nomenclature for 60 works in the prescribed proforma as per para 8 of the Government Order first read above and requested the orders of Government.
- 3. The Government after careful examination, accept the proposal of the Chief Engineer (Construction and Maintenance), Highways Department and accord sanction for change in nomenclature for 60 (Sixty) works as annexed to this order.

(By Order of the Governor)

S.K. Prabakar Additional Chief Secretary to Government (FAC)

To

The Chief Engineer (Construction & Maintenance),

Highways Department, Chennai-25.

The Pay and Accounts Officer (South/North/East), Chennai-35/79/8.

The Accountant General, Chennai-18/35.

The Director General, Highways Department, Chennai-25.

All Chief Engineers in Highways Department, Chennai.

All Treasury Officers.

### Copy to:-

O/o. the Hon'ble Chief Minister, Chennai-9.

The National Information Centre (NIC), Chennai-9.

The Director of Information and Public Relations, Chennai-9.

The Private Secretary to Chief Secretary to Government, Chennai-9

The Private Secretary to Additional Chief Secretary to Government (FAC), Highways & Minor Ports Department, Secretariat, Chennai-9.

The Finance (PW I)Department, Chennai-9.

The Resident Audit Officer / O/o. the Principal Accountant General, (General and Social Sector Audit) Tamil Nadu, Secretariat, Chennai - 9.

All Sections in Highways & Minor Ports Department, Chennai-9.

// Forwarded By Order //

Section Officer

29/1/19

# Annexure to G.O.(D) No.83, Highways and Minor Ports (HN2) Department, dated 30.05.2019.

## Change in Nomenclature in 2017-2018 Road Safety Works

As per G.O.(Ms) No. 48, Highways and Minor Ports (HN2) Department dated 28.03.2018											
			S1.	0-4	Before Revi	sion	After Revis	son			
SI. No	Circle	Division	No. in G.O	Categ- ory of road	Name of work as per G.O	A.S. Amount Rs.in. Lakhs	Revised Nomenclature	T.S. Amount Rs.in. Lakhs	Reason for the change in Nomenclature		
1	Tirupur	Karur	331	SH199	Providing metal crash barrier at Km14/2 of Vaiyampatty-Karur road (via) Mylampatty, Uppidamangalam (SH 199)	3.70	Providing metal crash barrier at Km13/4 of Vaiyampatty-Karur road (via) Mylampatty, Uppidamangalam (SH 199)	3.70			
2	Tirupur	Karur	28	ODR	Reconstruction of Slab culvert at km 0/6 of Modakkurichi- Savadipalayam road	25.00	Reconstruction of Slab culvert at km 1/6 of Modakkurichi- Savadipalayam road	25.00	The location of culvert was erroneously typed as km 0/6 instead of km 1/6.		
3	Villupuram	Cuddalore	92	SH	Widening from DL to ML from km 6/0-6/6 of Vridhachalam-Tholudur road including Junction Improvement at km 6/2 (14-15-BS85-21)	180.00	Widening from DL to ML from km 6/0-6/6 and strengthening from km 6/2-6/6 of Vridhachalam-Tholudur road including Junction Improvement at km 6/2 (14-15-BS85-21)	180.00	The Stretch from km 6/2-6/6 warrants strengthening and due for strengthening and hence included in the estimate within the available AS value.		
4	Coimbatore	Gobi	380	ODR	Providing Metal Crash Barrier in Siruvalur- Chettiyampalaya m road at Km 6/2 (LS)	9.10	Providing Metal Crash Barrier in Siruvalur- Chettiyampalaya m road at Km 5/2 (LS)	9.10	Typing Error		
5	Madurai	Madurai	125	SH	Improvements of Curve at km 18/6 of Madurai- Alagarkoil- Madurai road (SH 72A)	30.00	Improvements of Curve at km 18/6 of Madurai- Alagarkoil-Melur road (SH 72A)	30.00	Printing Error		

		·							
6	Madurai	Dindigul	684	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Dindigul Highways (C&M) Division	3.00	Providing Speed Breakers for State Highways Roads branching from NH in Dindigul Highways (C&M) Division	3.00	As per G.O Table Top Type Speed breakers is to be provided only in Other District roads (ODR).Hence normal speed breakers are provided in State Higways Roads.
7	Chennai	Chengalpattu	616	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Chengalpattu Highways (C&M) Division	6.00	Providing Speed Breakers for State Highways Roads branching from NH in Chengalpattu Highways(C&M) Division	6.00	Typographical error
8	Chennai	Chengalpattu	617	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Chengalpattu Highways (C&M) Division	8.00	Providing Speed Breakers for Major District Roads branching from NH in Chengalpattu Highways(C&M) Division	8.00	Typographical error
9	Chennai	Vellore	619	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Vellore Highways (C&M) Division	20.00	Providing Speed Breakers for State Highways Roads branching from NH in Vellore Highways(C&M) Division	20.00	Typographical error
10	Chennai	Vellore	620	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Vellore Highways (C&M) Division	7.00	Providing Speed Breakers for Major District Roads branching from NH in Vellore Highways(C&M) Division	7.00	Typographical error

/			-						
11	Chennai	Cheyyar	622	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Cheyyar Highways (C&M) Division	1.00	Providing Speed Breakers for State Highways Roads branching from NH in Cheyyar Highways(C&M) Division	1.00	Typographical error
12	Chennai	Vaniyambadi	624	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Vaniyambadi Highways (C&M) Division	1.00	Providing Speed Breakers for State Highways Roads branching from NH in Vaniyambadi Highways(C&M) Division	1.00	Typographical error
13	Chennai	Vaniyambadi	625	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Vaniyambadi Highways (C&M) Division	2.00	Providing Speed Breakers for Major District Roads branching from NH in Vaniyambadi Highways(C&M) Division	2.00	Typographical error
14	Chennai	Thiru- vannamalai	627	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Thiruvannamalai Highways (C&M) Division	3.00	Providing Speed Breakers for State Highways Roads branching from NH in Thiruvannamalai Highways(C&M) Division	3.00	Typographical error
15	Chennai	Thiru- vannamalai	628	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Thiruvannamalai Highways (C&M) Division	1.00	Providing Speed Breakers for Major District Roads branching from NH in Thiruvannamalai Highways(C&M) Division	1.00	Typographical error

	4 = 5								
16	Villupuram	Villupuram	630	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Villupuram Highways (C&M) Division	2.00	Providing Speed Breakers for State Highways Roads branching from NH in Villupuram Highways(C&M) Division	2.00	Typographical error
17	Villupuram	Villupuram	631	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Villupuram Highways (C&M) Division	7.00	Providing Speed Breakers for Major District Roads branching from NH in Villupuram Highways(C&M) Division	7.00	Typographical error
18	Villupuram	Cuddalore	633	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Cuddalore Highways (C&M) Division	9.00	Providing Speed Breakers for State Highways Roads branching from NH in Cuddalore Highways(C&M) Division	9.00	Typographical error
19	Villupuram	Cuddalore	634	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Cuddalore Highways (C&M) Division	5.00	Providing Speed Breakers for Major District Roads branching from NH in Cuddalore Highways(C&M) Division	5.00	Typographical error
20	Villupuram	Kallakurichi	636	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Kallakurichi Highways (C&M) Division	1.00	Providing Speed Breakers for State Highways Roads branching from NH in Kallakurichi Highways(C&M) Division	1.00	Typographical error

1										
	21	Villupuram	Ariyalur	638	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Ariyalur Highways (C&M) Division	2.00	Providing Speed Breakers fo State Highway: Roads branching from NH ir Ariyalur Highways(C&M) Division	r s 2 00	Typographical error
	22	Villupuram	Ariyalur	639	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Ariyalur Highways (C&M) Division	1.00	Providing Speed Breakers for Major District Roads branching from NH in Ariyalur Highways(C&M) Division	1.00	Typographical error
	23	Salem	Namakkal	642	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Namakkal Highways (C&M) Division	1.00	Providing Speed Breakers for State Highways Roads branching from NH in Namakkal Highways(C&M) Division	1.00	Typographical error
2	4	Salem	Namakkal	643	SH	Providing Speed Breakers (Table Top Type) and road furniture in Mohanur - Namakkal - Sendammangala m - Rasipuram Road (SH95) at Km. 29/4, 6 & 8 (16-BS64-5)	1.00	Providing Speed Breakers and road furniture in Mohanur - Namakkal - Sendammangala m - Rasipuram Road (SH95) at Km. 29/4, 6 & 8 (16-BS64-5)	1.00	Typographical error
25	S	Salem	Namakkal	644		Providing Speed Breakers (Table Top Type) and road furniture in Mohanur - Namakkal - Sendammangala m - Rasipuram Road (SH95) at Km.37/6,8 (16-BS64-44)	1.00	Providing Speed Breakers and road furniture in Mohanur - Namakkal - Sendammangala m - Rasipuram Road (SH95) at Km.37/6,8 (16- BS64-44)	1.00	Typographical error

26	Salem	Namakkal	645	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Namakkal Highways (C&M) Division	1.00	Providing Speed Breakers for Major District Roads branching from NH in Namakkal Highways(C&M) Division	1.00	Typographical error
27	Salem	Namakkal	646	MDR	Providing Speed Breakers (Table, Top Type) and road furniture in Nainamalai- Sendamangalam Road at km.0/6 (16-BS64-6)	2.00	Providing Speed Breakers and road furniture in Nainamalai- Sendamangalam Road at km.0/6 (16-BS64-6)	2.00	Typographical error
28	Salem	Namakkal	647	MDR	Providing Speed Breakers (Table Top Type) and road furniture in Nainamalai- Sendamangalam Road at km.3/10 (16-BS64-45)	2.00	Providing Speed Breakers and road furniture in Nainamalai- Sendamangalam Road at km.3/10 (16-BS64-45)	2.00	Typographical error
29	Salem	Namakkal	648	MDR	Providing Speed Breakers (Table Top Type) and road furniture in Nainamalai- Sendamangalam Road at km.4/4 (16-BS64-46)	2.00	Providing Speed Breakers and road furniture in Nainamalai- Sendamangalam Road at km.4/4 (16-BS64-46)	2.00	Typographical error
30	Tiruppur	Tiruppur	652	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Tiruppur Highways (C&M) Division	16.00	Providing Speed Breakers for State Highways Roads branching from NH in Tiruppur Highways(C&M) Division	16.00	Typographical error

1									
31	Tiruppur	Tiruppur	653	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Tiruppur Highways (C&M) Division	5.00	Providing Speed Breakers for Major District Roads branching from NH in Tiruppur Highways(C&M) Division	5.00	Typographical error
32	Tiruppur	Erode	655	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Erode Highways (C&M) Division	1.00	Providing Speed Breakers for State Highways Roads branching from NH in Erode Highways(C&M) Division	1.00	Typographical error
33	Tiruppur	Karur	656	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Karur Highways(C&M) Division	2.00	Providing Speed Breakers for State Highways Roads branching from NH in Karur Highways(C&M) Division	2.00	Typographical error
34	Tiruppur	Dharapuram	658	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Dharapuram Highways(C&M) Division	1.00	Providing Speed Breakers for Major District Roads branching from NH in Dharapuram Highways(C&M) Division	1.00	Typographical error
35	Coimbatore	Coimbatore	659	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Coimbatore Highways(C&M) Division	9.00	Providing Speed Breakers for State Highways Roads branching from NH in Coimbatore Highways(C&M) Division	9.00	Typographical error

			-						,
36	Coimbatore	Coimbatore	660	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Coimbatore Highways(C&M) Division	17.00	Providing Speed Breakers for Major District Roads branching from NH in Coimbatore Highways(C&M) Division	17.00	Typographical error
37	Coimbatore	Gobi	663	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Gobi Highways (C&M) Division	3.00	Providing Speed Breakers for State Highways Roads branching from NH in Gobi Highways(C&M) Division	3.00	Typographical error
38	Coimbatore	Gobi	664	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Gobi Highways (C&M) Division	2.00	Providing Speed Breakers for Major District Roads branching from NH in Gobi Highways(C&M) Division	2.00	Typographical error
39	Coimbatore	Uthagai	666	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Uthagai Highways (C&M) Division	3.00	Providing Speed Breakers for State Highways Roads branching from NH in Uthagai Highways(C&M) Division	3.00	Typographical error
40	Coimbatore	Uthagai	667	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Uthagai Highways (C&M) Division	3.00	Providing Speed Breakers for Major District Roads branching from NH in Uthagai Highways(C&M) Division	3.00	Typographical error

			,						
41	Trichy	Trichy	669	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Trichy Highways (C&M) Division	2.00	Providing Speed Breakers for Major District Roads branching from NH in Trichy Highways(C&M) Division	2.00	Typographical error
42	Trichy	Thanjavur	671	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Thanjavur Highways (C&M) Division	6.00	Providing Speed Breakers for State Highways Roads branching from NH in Thanjavur Highways(C&M) Division	6.00	Typographical error
43	Trichy	Thanjavur	672	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Thanjavur Highways (C&M) Division	3.00	Providing Speed Breakers for Major District Roads branching from NH in Thanjavur Highways(C&M) Division	3.00	Typographical error
44	Trichy	Pudukkottai	674	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Pudukkottai Highways (C&M) Division	2.00	Providing Speed Breakers for State Highways Roads branching from NH in Pudukkottai Highways(C&M) Division	2.00	Typographical error
45	Trichy	Tiruvarur	676	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Tiruvarur Highways (C&M) Division	4.00	Providing Speed Breakers for State Highways Roads branching from NH in Tiruvarur Highways(C&M) Division	4.00	Typographical error

46	Trichy	Nagapat- tinam	678	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Nagapattinam Highways (C&M) Division	2.00	Providing Speed Breakers for State Highways Roads branching from NH in Nagapattinam Highways(C&M) Division	2.00	Typographical error
47	Trichy	Nagapat- tinam	679	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Nagapattinam Highways (C&M) Division	4.00	Providing Speed Breakers for Major District Roads branching from NH in Nagapattinam Highways(C&M) Division	4.00	Typographical error
48	Madurai	Madurai	681	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Madurai Highways (C&M) Division	4.00	Providing Speed Breakers for State Highways Roads branching from NH in Madurai Highways(C&M) Division	4.00	Typographical error
49	Madurai	Madurai	682	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Madurai Highways (C&M) Division	4.00	Providing Speed Breakers for Major District Roads branching from NH in Madurai Highways(C&M) Division	4.00	Typographical error
50	Madurai	Dindigul	684	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Dindigul Highways (C&M) Division	3.00	Providing Speed Breakers for State Highways Roads branching from NH in Dindigul Highways(C&M) Division	3.00	Typographical error

1			-						
	# P.S.								
51	Madurai	Dindigul	685	SH	Providing speed breaker at km 1/8, 1/10 and 2/2 of Dindigul Vathalagundu Theni Cumbum Kumuli Road (SHU90) (Dindigul) (16-BS64-55)		Providing speed breaker at kn 1/8, 1/10 and 2/2 of Dindigu Vathalagundu Theni Cumbum Kumuli Road (SHU90) (Dindigul) (16- BS64-55)	1.00	Typographical error
52	Madurai	Theni	686	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Theni Highways (C&M) Division	5.00	Providing Speed Breakers for State Highways Roads branching from NH in Theni Highways(C&M) Division	5.00	Typographical error
53	Madurai	Theni	687	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Theni Highways (C&M) Division	3.00	Providing Speed Breakers for Major District Roads branching from NH in Theni Highways(C&M) Division	3.00	Typographical error
54	Madurai	Sivagangai	689	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Sivagangai Highways (C&M) Division	1.00	Providing Speed Breakers for State Highways Roads branching from NH in Sivagangai Highways(C&M) Division	1.00	Typographical error
55	Madurai	Sivagangai	690	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Sivagangai Highways (C&M) Division	5.00	Providing Speed Breakers for Major District Roads branching from NH in Sivagangai Highways(C&M) Division	5.00	Typographical error

	1 1								
56	Tirunelveli	Tenkasi	694	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Tenkasi Highways (C&M) Division	2.00	Providing Speed Breakers for State Highways Roads branching from NH in Tenkasi Highways(C&M) Division	2.00	Typographical error
57	Tirunelveli	Tenkasi	695	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Tenkasi Highways (C&M) Division	5.00	Providing Speed Breakers for Major District Roads branching from NH in Tenkasi Highways(C&M) Division	5.00	Typographical error
58	Tirunelveli	Thoothukudi	697	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads and Other District Roads branching from NH in Tuticorin Highways (C&M) Division	2.00	Providing Speed Breakers for State Highways Roads and Other District Roads branching from NH in Tuticorin Highways(C&M) Division	2.00	Typographical error
59	Tirunelveli	Nagarcoil	698	SH	Providing Speed Breakers (Table Top Type) for State Highways Roads branching from NH in Nagercoil Highways (C&M) Division	5.00	Providing Speed Breakers for State Highways Roads branching from NH in Nagercoil Highways(C&M) Division	5.00	Typographical error
60	Tirunelveli	Nagarcoil	699	MDR	Providing Speed Breakers (Table Top Type) for Major District Roads branching from NH in Nagarcoil Highways (C&M) Division	14.00	Providing Speed Breakers for Major District Roads branching from NH in Nagarcoil Highways(C&M) Division	14.00	Typographical error

S.K. Prabakar Additional Chief Secretary to Government (FAC)

//True Copy//

Section Officer

21/5/4